

235 East 5th Street, New York, NY

Reading#	Time	Component	Substrate	Side	Condition	Site	Floor	Room	Results	Depth	Action	PbC	PbC Err	PbL	F L Err	PbK	PbKErr
1	2/6/2020 12:48											2.8	0	0.45	0	0	0
2	2/6/2020 12:48			CAL.					Negative	1.12	1	0.9	0.1	0.9	0.1	0.7	0.8
3	2/6/2020 12:49			CAL.					Negative	1.15	1	0.9	0.1	0.9	0.1	0.6	0.8
4	2/6/2020 12:50			CAL.					Positive	1.19	1	1	0.1	1	0.1	0.16	0.39
5	2/6/2020 13:06	WALL	PLASTER	A	Fair	235 E 5TH	FIRST	HALL	Negative	1	1	0	0.02	0	0.02	-0.02	1
6	2/6/2020 13:06	WALL	PLASTER	B	Fair	235 E 5TH	FIRST	HALL	Negative	5.94	1	0.02	0.06	0.02	0.06	0.3	1.34
7	2/6/2020 13:06	WALL	PLASTER	C	Fair	235 E 5TH	FIRST	HALL	Negative	1	1	0	0.02	0	0.02	-0.16	1.79
8	2/6/2020 13:07	WALL	PLASTER	D	Fair	235 E 5TH	FIRST	HALL	Negative	1	1	0	0.02	0	0.02	0.09	1.29
9	2/6/2020 13:07	BASEBOARD	WOOD	A	Fair	235 E 5TH	FIRST	HALL	Negative	3.58	1	0.16	0.26	0.16	0.26	0.8	2
10	2/6/2020 13:07	DOOR	METAL	A	Fair	235 E 5TH	FIRST	HALL	Negative	1	1	0	0.02	0	0.02	-0.29	2.78
11	2/6/2020 13:07	DOOR CASING	METAL	A	Fair	235 E 5TH	FIRST	HALL	Negative	1	1	0	0.02	0	0.02	0.6	3.8
12	2/6/2020 13:08	TREAD	METAL	C	Fair	235 E 5TH	FIRST	HALL	Negative	1	1	0	0.02	0	0.02	-0.05	3.46
13	2/6/2020 13:08	RISER	METAL	C	Fair	235 E 5TH	FIRST	HALL	Negative	1.88	1	0.06	0.11	0.06	0.11	0.04	1.76
14	2/6/2020 13:08	STRINGER	WOOD	C	Fair	235 E 5TH	FIRST	HALL	Negative	3.46	1	0.5	0.5	0.5	0.5	1	2.3
15	2/6/2020 13:09	RAIL	WOOD	C	Fair	235 E 5TH	FIRST	HALL	Negative	1	1	0.01	0.04	0.01	0.04	0.4	2.1
16	2/6/2020 13:09	BALUSTER	METAL	C	Fair	235 E 5TH	FIRST	HALL	Negative	2.5	1	0.07	0.13	0.07	0.13	0.16	3.62
17	2/6/2020 13:09	NEWEL POST	METAL	C	Fair	235 E 5TH	FIRST	HALL	Null	3.13	1	0.17	0.18	0.17	0.18	-0.21	2.59
18	2/6/2020 13:09	NEWEL POST	METAL	C	Fair	235 E 5TH	FIRST	HALL	Negative	2.19	1	-0.4	1.27	0.11	0.06	-0.4	1.27
19	2/6/2020 13:10	CEILING	PLASTER		Fair	235 E 5TH	FIRST	HALL	Null	1	1	0	0.06	0	0.06	2.5	12.1
20	2/6/2020 13:10	CEILING	PLASTER		Fair	235 E 5TH	FIRST	HALL	Null	1	1	0	0.02	0	0.02	0.22	1.78
21	2/6/2020 13:10	CEILING	PLASTER		Fair	235 E 5TH	FIRST	HALL	Null	1	1	0	0.02	0	0.02	0.6	2.6
22	2/6/2020 13:10	CEILING	PLASTER		Fair	235 E 5TH	FIRST	HALL	Null	1	1	0	0.02	0	0.02	0.5	3
23	2/6/2020 13:11	CEILING	PLASTER		Fair	235 E 5TH	FIRST	HALL	Negative	3.32	1	0.01	0.04	0.01	0.04	0.3	1.17
24	2/6/2020 13:12	TRIM	METAL	C	Fair	235 E 5TH	FIRST	HALL	Negative	1	1	0	0.02	0	0.02	-0.04	2.32
25	2/6/2020 13:13	WINDOW CASING	WOOD	A	Fair	235 E 5TH	FIRST	HALL	Negative	1	1	0	0.02	0	0.02	0.8	1
26	2/6/2020 13:24	WALL	PLASTER	A	Fair	235 E 5TH	SECOND	HALL	Negative	1	1	0	0.02	0	0.02	-0.07	1.74
27	2/6/2020 13:25	WALL	PLASTER	B	Fair	235 E 5TH	SECOND	HALL	Negative	1	1	0	0.02	0	0.02	0.7	1
28	2/6/2020 13:25	WALL	PLASTER	C	Fair	235 E 5TH	SECOND	HALL	Negative	1	1	0	0.02	0	0.02	0.4	1.1
29	2/6/2020 13:25	WALL	PLASTER	D	Fair	235 E 5TH	SECOND	HALL	Negative	1	1	0	0.02	0	0.02	0.3	1.28
30	2/6/2020 13:25	BASEBOARD	WOOD	A	Fair	235 E 5TH	SECOND	HALL	Negative	1	1	0	0.02	0	0.02	0.21	1.96
31	2/6/2020 13:26	TREAD	METAL	C	Fair	235 E 5TH	SECOND	HALL	Negative	1	1	0	0.02	0	0.02	-0.49	2.83
32	2/6/2020 13:27	RISER	METAL	C	Fair	235 E 5TH	SECOND	HALL	Negative	2.32	1	0.13	0.18	0.13	0.18	-0.03	1.91
33	2/6/2020 13:27	STRINGER	WOOD	C	Fair	235 E 5TH	SECOND	HALL	Positive	5.41	1	1.9	0.9	1.9	0.9	2.3	1.9
34	2/6/2020 13:27	RAIL	WOOD	C	Fair	235 E 5TH	SECOND	HALL	Negative	1	1	0.01	0.04	0.01	0.04	0.6	2.2
35	2/6/2020 13:27	BALUSTER	METAL	C	Fair	235 E 5TH	SECOND	HALL	Negative	1.38	1	0.06	0.09	0.06	0.09	-0.07	3.13
36	2/6/2020 13:27	NEWEL POST	METAL	C	Fair	235 E 5TH	SECOND	HALL	Negative	2.43	1	0.12	0.17	0.12	0.17	-0.97	3.27
37	2/6/2020 13:32	CEILING	PLASTER	C	Fair	235 E 5TH	SECOND	HALL	Negative	1	1	0	0.02	0	0.02	0.4	1.1
38	2/6/2020 13:33	WALL	PLASTER	A	Fair	235 E 5TH	THIRD	HALL	Negative	1	1	0	0.02	0	0.02	-0.2	1.87
39	2/6/2020 13:33	WALL	PLASTER	B	Fair	235 E 5TH	THIRD	HALL	Negative	2.28	1	0.01	0.02	0.01	0.02	-0.28	1.27
40	2/6/2020 13:33	WALL	PLASTER	C	Fair	235 E 5TH	THIRD	HALL	Negative	1	1	0	0.02	0	0.02	0.6	1

Reading#	Time	Component	Substrate	Side	Condition	Site	Floor	Room	Results	Depth	Action	PbC	PbC Err	PbL	P L Err	PbK	PbKErr
41	2/6/2020 13:34	WALL	PLASTER	D	Fair	235 E 5TH	THIRD	HALL	Negative	1	1	0	0.02	0	0.02	0.7	0.9
42	2/6/2020 13:34	BASEBOARD	WOOD	A	Fair	235 E 5TH	THIRD	HALL	Negative	2.06	1	0.15	0.18	0.15	0.18	0.6	2.2
43	2/6/2020 13:34	TREAD	METAL	C	Fair	235 E 5TH	THIRD	HALL	Negative	1	1	0	0.02	0	0.02	-0.32	3.28
44	2/6/2020 13:35	RISER	METAL	C	Fair	235 E 5TH	THIRD	HALL	Negative	3.45	1	0.4	0.4	0.4	0.4	0.6	1.9
45	2/6/2020 13:35	STRINGER	WOOD	C	Fair	235 E 5TH	THIRD	HALL	Positive	2.86	1	2	0.9	2	0.9	1.9	2.5
46	2/6/2020 13:35	RAIL	WOOD	C	Fair	235 E 5TH	THIRD	HALL	Negative	1	1	0.02	0.04	0.02	0.04	0.6	2.3
47	2/6/2020 13:35	BALUSTER	METAL	C	Fair	235 E 5TH	THIRD	HALL	Negative	1.18	1	0.03	0.06	0.03	0.06	0.07	3.5
48	2/6/2020 13:35	NEWEL POST	METAL	C	Fair	235 E 5TH	THIRD	HALL	Negative	1	1	0.03	0.05	0.03	0.05	-0.49	3.37
49	2/6/2020 13:36	CEILING	PLASTER		Fair	235 E 5TH	THIRD	HALL	Null	1	1	0	0.02	0	0.02	1	2.2
50	2/6/2020 13:36	CEILING	PLASTER		Fair	235 E 5TH	THIRD	HALL	Negative	1	1	0	0.02	0	0.02	0.5	1.1
51	2/6/2020 13:37	WALL	PLASTER	A	Fair	235 E 5TH	FOURTH	HALL	Negative	1	1	0	0.02	0	0.02	0.08	1.14
52	2/6/2020 13:37	WALL	PLASTER	B	Fair	235 E 5TH	FOURTH	HALL	Negative	1	1	0	0.02	0	0.02	0.5	1.1
53	2/6/2020 13:37	WALL	PLASTER	C	Fair	235 E 5TH	FOURTH	HALL	Null	1	1	0	0.02	0	0.02	0.9	2.6
54	2/6/2020 13:37	WALL	PLASTER	C	Fair	235 E 5TH	FOURTH	HALL	Negative	1	1	0	0.02	0	0.02	0.14	1.07
55	2/6/2020 13:38	WALL	PLASTER	D	Fair	235 E 5TH	FOURTH	HALL	Negative	1	1	0	0.02	0	0.02	0.3	1.26
56	2/6/2020 13:38	BASEBOARD	WOOD	A	Fair	235 E 5TH	FOURTH	HALL	Negative	1	1	0.04	0.06	0.04	0.06	1	1.9
57	2/6/2020 13:38	TREAD	METAL	C	Fair	235 E 5TH	FOURTH	HALL	Negative	1	1	0	0.02	0	0.02	0.15	3.68
58	2/6/2020 13:38	RISER	METAL	C	Fair	235 E 5TH	FOURTH	HALL	Negative	2.38	1	0.22	0.24	0.22	0.24	0.3	1.93
59	2/6/2020 13:39	STRINGER	WOOD	C	Fair	235 E 5TH	FOURTH	HALL	Positive	4.04	1	3.7	2.5	3.7	2.5	3.4	4.8
60	2/6/2020 13:39	RAIL	WOOD	C	Fair	235 E 5TH	FOURTH	HALL	Negative	1	1	0.01	0.03	0.01	0.03	0.3	2.11
61	2/6/2020 13:39	BALUSTER	METAL	C	Fair	235 E 5TH	FOURTH	HALL	Negative	1	1	0.02	0.04	0.02	0.04	0.5	3.6
62	2/6/2020 13:39	NEWEL POST	METAL	C	Fair	235 E 5TH	FOURTH	HALL	Negative	1.14	1	0.04	0.05	0.04	0.05	-0.16	2.72
63	2/6/2020 13:40	CEILING	PLASTER		Fair	235 E 5TH	FOURTH	HALL	Negative	1	1	0	0.02	0	0.02	0.5	1.1
64	2/6/2020 13:40	WALL	PLASTER	A	Fair	235 E 5TH	FIFTH	HALL	Negative	1	1	0	0.02	0	0.02	0.4	1.1
65	2/6/2020 13:41	WALL	PLASTER	B	Fair	235 E 5TH	FIFTH	HALL	Negative	1	1	0	0.02	0	0.02	0.01	1.25
66	2/6/2020 13:41	WALL	PLASTER	C	Fair	235 E 5TH	FIFTH	HALL	Null	1	1	0	0.02	0	0.02	0.9	2.7
67	2/6/2020 13:41	WALL	PLASTER	C	Fair	235 E 5TH	FIFTH	HALL	Negative	1	1	0	0.02	0	0.02	0.3	1.04
68	2/6/2020 13:42	WALL	PLASTER	D	Fair	235 E 5TH	FIFTH	HALL	Negative	1	1	0	0.02	0	0.02	0.26	1.25
69	2/6/2020 13:42	BASEBOARD	WOOD	A	Fair	235 E 5TH	FIFTH	HALL	Negative	4.05	1	0.25	0.34	0.25	0.34	0.7	1.9
70	2/6/2020 13:42	TREAD	METAL	C	Fair	235 E 5TH	FIFTH	HALL	Negative	1	1	0.01	0.02	0.01	0.02	0.1	1.31
71	2/6/2020 13:42	RISER	METAL	C	Fair	235 E 5TH	FIFTH	HALL	Negative	1.05	1	0.05	0.07	0.05	0.07	0.7	3.6
72	2/6/2020 13:43	STRINGER	WOOD	C	Fair	235 E 5TH	FIFTH	HALL	Negative	3.38	1	0.22	0.28	0.22	0.28	-0.05	2.81
73	2/6/2020 13:43	RAIL	WOOD	C	Fair	235 E 5TH	FIFTH	HALL	Negative	1.59	1	0.01	0.05	0.01	0.05	0.6	1.9
74	2/6/2020 13:43	BALUSTER	METAL	C	Fair	235 E 5TH	FIFTH	HALL	Negative	1.01	1	0.03	0.05	0.03	0.05	0.6	3.4
75	2/6/2020 13:43	NEWEL POST	METAL	C	Fair	235 E 5TH	FIFTH	HALL	Negative	2.27	1	0.13	0.17	0.13	0.17	0.6	3.6
76	2/6/2020 13:44	CEILING	PLASTER		Fair	235 E 5TH	FIFTH	HALL	Negative	1	1	0	0.02	0	0.02	0.8	0.9
77	2/6/2020 14:18			CAL.					Negative	1.1	1	0.9	0.1	0.9	0.1	0.08	0.48
78	2/6/2020 14:19			CAL.					Positive	1.18	1	1.1	0.1	1.1	0.1	0.3	0.52
79	2/6/2020 14:20			CAL.					Positive	1.18	1	1	0.1	1	0.1	0.27	0.37