

# ENVIRO-PROBE, INC.

6 Hollywood Court, Suite C, 2<sup>nd</sup> floor  
South Plainfield NJ 07080  
732-494-4600 [enviroprob@aol.com](mailto:enviroprob@aol.com)

## LEAD DUST WIPE ANALYSIS REPORT

Client: AAA Lead Professionals  
6 White Dove Court  
Lakewood, NJ 08701

Received Date: 02/11/20  
Analyzed Date: 02/11/20  
Reported Date: 02/12/20  
EPI Case #: 20-596

Sampling Location: 235 East 5th Street, New York NY  
Sampled By: Yaakov Beer  
Sampling Date: 02/06/20  
Sampling Time: na

Sample Number	Lab ID Number	Sampling Location	Surface Type	Wipe Area (inches)	Wipe Area (inches)	Area (ft <sup>2</sup> )	Total Micrograms (ug)	Micrograms per square ft. (ug/ft <sup>2</sup> )
1	6070	1st floor hall front	Floor	12	12	1.00	<5.0	<5.0
2	6071	1st floor hall rear	Floor	12	12	1.00	<5.0	<5.0
3	6072	2nd floor hall front	Floor	12	12	1.00	<5.0	<5.0
4	6073	2nd floor hall rear	Floor	12	12	1.00	<5.0	<5.0
5	6074	3rd floor hall front	Floor	12	12	1.00	<5.0	<5.0
6	6075	3rd floor hall rear	Floor	12	12	1.00	<5.0	<5.0
7	6076	4th floor hall front	Floor	12	12	1.00	<5.0	<5.0
8	6077	4th floor hall rear	Floor	12	12	1.00	<5.0	<5.0
9	6078	5th floor hall front	Floor	12	12	1.00	<5.0	<5.0
10	6079	5th floor hall rear	Floor	12	12	1.00	<5.0	<5.0
11	6080	Music room	Floor	12	12	1.00	<5.0	<5.0

Reporting Limit (RL) - 5.0 ug Total Pb.

Samples are not collected by Enviro-Probe. Sample location, description, area, etc. was provided by the client.

Results apply to samples as received. Sample results are not corrected for blanks. Samples received in good condition, except if noted.


Samples below quantitation limit (RL) are reported with less than sign (<). Test results meet all NELAC and quality control requirements.

This report shall not be reproduced except in full, without the written approval of Enviro-Probe.

Method: EPA SW846 7000B ASTM E1644-17

AIHA-LAP # 100247 NYSDOH ELAP # 11404

Analyzed by: VM

  
Lyudmila Kogan  
Technical Director

